



## BUILDING THE LOCKHEED P-38 LIGHTNING


EEFORE STARTING CONSTRUCTION: Study plan carefully, work accurately. Obtain the following tools and materials: - razor blade, about 50 small common pins, pair of pliers, sandpaper, and a sheet of wax paper. Pin wax paper over plan to prevent frames from adhering to plan. Use drawing board, bread board, cardboard, etc. as base (a balsa base is better if obtainable). Strip panel cut balsa. Use a straight edge to guide razor blade. Sandpaper rough edges of stock smooth. Use thick quick drying cement to fasten balsa parts together.


Follow printed directions given on plan, start with Step One, then Step Two, etc. Refer to this sheet for illustrations of succeeding steps, being sure to follow notes given here. For instance, instructions given on plan call for covering each frame as it is built. Instead it is best to build all frames first, then cover them as indicated on this sheet. On reverse side of this sheet are many general methods of cementing frames together, cutting out ribs and formers, covering frames and assembling. Illustrations given are not of model being built.




Copyright 1940, 1942 by Paul K. Guillow

O








AND FIVE Hudder frame

make two



Rest center bedy on table with time on blocks un

**3 9** 

Omment vings to senter bod;

**4**)

